

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		111.18	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		163,216	
Heat Type	1		FORCED H/A	AYB		1958	
AC Type	01		NONE	EYB		1975	
Bedrooms	3			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		43	
Total Rooms	5			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		57	
Basement Floor	12		CONCRETE	Apprais Val		93,000	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,090		22.24	24,238	
EFP	ENCL PORCH	0	144		33.20	4,781	
FFL	1ST FLOOR	1,090	1,090		111.18	121,189	
GAR	GARAGE	0	280		44.47	12,452	
PAT	PATIO	0	96		5.79	556	

Ttl. Gross Liv/Lease Area:		1,090	2,700	1,468	163,216		
----------------------------	--	-------	-------	-------	---------	--	--

