

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	384			
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	8		PLYWD PANL					
Interior Wall 2				Adj. Base Rate:				91.99
Interior Floor 1	3		HARDWOOD	Replace Cost				233,091
Interior Floor 2				AYB				1955
Heat Fuel	1		OIL	EYB				1975
Heat Type	1		FORCED H/A	Dep Code				AV
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	1			Dep %				43
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	6			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				57
Extra Kitchens	0			Apprais Val				132,900
Frame	1		WOOD	Dep % Ovr				0
Basement Floor				Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	1			Cost to Cure Ovr Comment				
Fireplaces	1							

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description		Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value					
BMT	BASEMENT		0	816		18.37	14,994					
EFP	ENCL PORCH		0	180		27.60	4,967					
FFL	1ST FLOOR		1,486	1,486		91.99	136,690					
GAR	GARAGE		0	384		36.89	14,166					
OFF	OPEN PORCH		0	84		8.76	736					
TQS	3/4 STORY		612	816		68.99	56,295					
WDK	WOOD DECK		0	404		12.98	5,243					

Ttl. Gross Liv/Lease Area:				2,098	4,170	2,534	233,091
----------------------------	--	--	--	-------	-------	-------	---------

