

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	560		
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		131.67	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		147,602	
Heat Type	5		STEAM	AYB		1950	
AC Type	01		NONE	EYB		1981	
Bedrooms	3			Dep Code		AG	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		37	
Total Rooms	6			Functional ObsInc			
Bath Style	A		AVERAGE	External ObsInc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		63	
Basement Floor	12		CONCRETE	Apprais Val		93,000	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	560		26.33	14,747
EFP	ENCL PORCH	0	24		38.40	922
FFL	1ST FLOOR	560	560		131.67	73,735
OSP	SCRN PORCH	0	144		20.12	2,897
TQS	3/4 STORY	420	560		98.75	55,301

Ttl. Gross Liv/Lease Area:		980	1,848	1,121		147,602
----------------------------	--	-----	-------	-------	--	---------

