

No. 88 SLUMBER LANE

Street SPRINGFIELD

Owner

Joyce Stavros

S. R.

Date	Work Done
09/24/2017	Service pipe laid by REPAIRED SERVICE – W. BRAULT

BUFFALO BOX IN STREET OVER 1" IK


- 59'-4" OUT FROM HOUSE
- 34'-1" S OF N LINE OF HOUSE
- 13'-4" N OF S LINE OF HOUSE
- 50'-6" S OF S LINE OF # 96

54'-4" 3/4" C.T.

3'-0" 1" C.T. 9/24/17

#88

#196



1 3/4" x 1"
CMP x CMP

59'-4"

3'-0"

13'-4"

34'-1"

50'-6"

6" W



1" IKICORP
REPAIR CLAMP
w/ 1" OUTLET

Slumber Ln