OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ackground	Data		VII	*************************	v.a				
bwatershed: MP Date & Time: 9:38 5/23/07			Outfall ID:	mR-10)					
Date & Time:	9:38	Form completed by: Ses MAR								
Temperature (°F)): 65°	Rainfall (in.): Last 24 hours: Last 48 hours:								
Camera: Lonale			Photo #s: 100-0386 (MR-010)							
DIAMETER (IN)	MATERIAL	FLO	W	DESCRI	PTION	<u>LAI</u>	ND USE I	V AREA	
Diameter:	Ŋ R	СР СМР	Depth: ir	1.	Trickle		☐ Industrial		Open Space	
24_in.	□ PV	VC HDPE	Width: in	1.	☐ Moderat	e	Urban Residentia	ı 🗀	Institutional	
	☐ St	teel Corr. Plastic			☐ Substant	tial	Suburban Resider	ntial Ot	her:	
	□ O ₁	ther:			☐ No Flow	7	☐ Commercial			
· From C · Headwall		istance and bearing if nece								
indicator	CHECK if Present	29/08 9 : DESCRIPT	: 10 am	0" ~	ain		IVE SEVERITY IN	IDEX (1-3		
Odor		Sewage Rar Petroleum/gas Sulfide Oth	ncid/sour ner:	☐ 1 – Faint		☐ 2 – Easily detected		3 – Noticeable from a distance		
Color		☐ Clear ☐ Bro ☐ Gray ☐ Yel ☐ Green ☐ Ora ☐ Red ☐ Othe	llow inge	1	aint colors sample ttle	2 – Clearly visible in sample bottle		3 - C	learly visible in outfall w	
Turbidity		See sever	rity	☐ 1 – S cloudine	_	□ 2 – 0	2 – Cloudy		paque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheen Other:			ew/slight; ot obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)		obv	ome; origin clear (e.g., vious oil sheen, suds, or ating sanitary materials)	
INDICATOR	Prese	ent	DESC racking or Chipp	RIPTION	Peeling F	Paint		COMME	NTS	
Outfall Damage		Corrosion								
Deposits/Stains		Oily Flo	Oily Flow Line Paint Other:							
Abnormal Vegetation										
Poor pool quality [

Pipe benthic

growth

☐ Brown

☐ Orange

☐ Green

Other: