OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET



Subwatershed:	MR		Outfall ID:	MI	2-22	Monte.			
Jate & Time: 11:44 5/9/07			Form completed by: SCS/mAS						
Temperature (°F):			Rainfall (in.): Last 24 hours: Last 48 hours:						
Camera:			Photo #s: 3656 (MR-022)						
DIAMETER (IN)	MATERIAL	FLOW		DESCRI			D USE IN AREA	
iameter:	X R	СР 🔲 СМР	Depth: in.		☐ Trickle		☐ Industrial	☐ Open Space	
\& in.	P\	C HDPE	Width: in.		☐ Moderat	e	☐ Urban Residential	☐ Institutional	
	□ St	eel Corr. Plastic			☐ Substant	ial	Suburban Resident	ial Other:	
	Ot	her:			No Flow		Commercial		
Notes (e.g, Acce	ess to outfall, d	istance and bearing if nece	essary, unable to lo	cate, etc):					
							_		
H		same as Mr-2(
V	Vovo			as Mr-2(
						10	-50	em naterial.	
					1-10	210	V	,	
					Ul 12	71	X K	, log	
					U/2	MS	7	ele from en le	
		1541 Mar 100 (1881 Mar 1981 M		No. 10 Control of the	U/2	45	-50	en material. i pe de from cul ve	
				- Old Mildelphagan ar represent	M	43	7 ~ ~ ~ ~ ~	de from cul ve	
DICATOR	CHECK if Present	DESCRIP	TION		W12		TIVE SEVERITY INC		
JDICATOR Odor			ncid/sour	□ 1 – F		RELA			
	Present	Sewage Rar	ncid/sour ner: own llow ange	☐ 1 – F		RELA	Easily detected Clearly visible in	DEX (1-3) 3 – Noticeable from a	
Odor	Present	Sewage	neid/sour ner: pwn llow ange er:	☐ 1 – F	Faint Faint colors sample ttle Slight	RELA □ 2 − □	Easily detected Clearly visible in bottle	DEX (1-3) 3 - Noticeable from a distance 3 - Clearly visible in outfal	
Odor Color	Present	Sewage Rar Petroleum/gas Sulfide Oth Clear Bro Gray Yel Green Ora Red Othe	neid/sour ner: own llow ange er: rity er, etc.)	1 - F	Faint Faint colors sample ttle Slight		Easily detected Clearly visible in bottle	DEX (1-3) 3 - Noticeable from a distance 3 - Clearly visible in outfal flow	
Odor Color Turbidity Floatables -Does Not Include	Present	Sewage Rar Petroleum/gas Sulfide Oth Clear Bro Gray Yel Green Ora Red Oth See sever Sewage (Toilet Pape	neid/sour ner: own llow ange er: rity er, etc.)	1 - F	Faint colors sample tttle Slight ess		Easily detected Clearly visible in bottle Cloudy Some; indications of igin (e.g., possible	DEX (1-3) 3 - Noticeable from a distance 3 - Clearly visible in outfal flow 3 - Opaque 3 - Some; origin clear (e.g., obvious oil sheen, suds, o	
Odor Color Turbidity Floatables -Does Not Include	Present	Sewage Rar Petroleum/gas Sulfide Oth Clear Bro Gray Yel Green Ora Red Othe See sever Sewage (Toilet Pape Suds Petroleum (oil sheen Other:	neid/sour ner: own llow ange er: rity er, etc.)	1 - F	Faint colors sample tttle Slight ess		Easily detected Clearly visible in bottle Cloudy Some; indications of igin (e.g., possible	DEX (1-3) 3 - Noticeable from a distance 3 - Clearly visible in outfal flow 3 - Opaque 3 - Some; origin clear (e.g., obvious oil sheen, suds, o	

INDICATOR	CHECK if Present	DESCRIPTION	COMMENTS		
Outfall Damage		Spalling, Cracking or Chipping Peeling Paint Corrosion			
Deposits/Stains	Ø	Oily Plow Line Paint Other:			
Abnormal Vegetation	D	☐ Excessive ☐ Inhibited	Sime moss		
Poor pool quality		Odors Colors Floatables Oil Sheen Suds Excessive Algae Other:	suds due to colvert for		
Pipe benthic growth		☐ Brown ☐ Orange ☐ Green ☐ Other:	line green stuff		