## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Background Data										
ibwatershed:		MZ		Outfall ID: MR-37						
Date & Time:	Date & Time: 10:05 5/23/07			Form completed by: SCS MAK						
Temperature (°F)		Rainfall (in.): Last 24 hours:   Last 48 hours:								
Camera:	COD	ak	Photo #s:	Photo #s: 100-0391 (MR-037)						
DIAMETER (IN) MATERIAL			FLOV	FLOW <u>DESCRIPTION</u>			LAN	LAND USE IN AREA		
Diameter:	□ RC	СР □ СМР	Depth: in.		☐ Trickle		☐ Industrial		Open Space	
24_ in.	□ PV	C HDPE	Width: in.		☐ Moderate	e l	Urban Residential		☐ Institutional	
	☐ Ste	eel Corr. Plastic			☐ Substantial		Suburban Residential		Other:	
	Ot	her:			No Flow	,	☐ Commercial			
Notes (e.g, Acce	ess to outfall, di	istance and bearing if nece	essary, unable to l	locate, etc):						
From My										
· From My · Flored end										
· Libred end										
5/29/06 8:45 BTOL D' rain 48hs										
8/29/06 8:45 BTOL D' rain 48hrs										
INDICATOR	CHECK if Present	DESCRIPT	rion			RELAT	TIVE SEVERITY IN	DEX (1	L-3) is a second of the second	
			ncid/sour				Easily detected		3 – Noticeable from a	
Odor		☐ Petroleum/gas ☐ Sulfide ☐ Oth	30r.	□ 1 – F		☐ 2 – H			distance	
		Clear Bro		+						
Color		☐ Gray ☐ Yel	llow		amnie i		Clearly visible in		3 – Clearly visible in outfall	
1	_	Green Ora		e bot		sample l	bottle		flow	
Turbidity		See sever	rity			2 – Cloudy		3	– Opaque	
		☐ Sewage (Toilet Pape		cloudine	cloudiness					
Floatables -Does Not		Sewage (Toffet Pape	r, etc.)	☐ 1 - F	ew/slight;				- Some; origin clear (e.g., obvious oil sheen, suds, or	
Include Trash!!		Petroleum (oil sheen	1		ot obvious OII		rigin (e.g., possible ads or oil sheen)		floating sanitary materials)	
114511::										
INDICATOR	CHECK Prese		DESCR	IPTION				сом	MENTS	
Outfall Damage		Spalling, Ci								
Deposits/Stains	, 0	Oily Flo	w Line Paint Other:							
Abnormal Vegetation		☐ Excessive [	☐ Excessive ☐ Inhibited					nazen eta arken eta a		
Pipe benthic growth		☐ Brown [	☐ Brown ☐ Orange ☐ Green ☐ Other:							