

## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Bac		كالكنتان التكاف المتناطعات كالمساحد والمساوية								
bwatershed:	D. R.		Outfall ID: PB-1							
⊿ate & Time:	2:4	15/3/07	Form completed by: SCS WAK							
Temperature (°F):	70		Rainfall (in.): Last 24 hours:   Last 48 hours: .15							
Camera: 100	034	<u> </u>	Photo #s: (PB-O11)							
DIAMETER (I	N)	MATERIAL	FLOW		DESCRI	PTION	LAI	ND US	E IN AREA	
Diameter:	₩ RC	Р СМР	Depth: in.		☐ Trickle		☐ Industrial		☐ Open Space	
<b>Z</b> 4in.	☐ PV	C HDPE	Width: in.	Moder:		te	☐ Urban Residentia	1	☐ Institutional	
	☐ Ste	el Corr. Plastic			☐ Substantial		Suburban Residentia		1 Other:	
	☐ Otl	ner:			☐ No Flow		☐ Commercial			
· From C · Culvert · Headwall	В									
	CHECK if Present	9/2/08 DESCRIP	[li30	1 Am			「ん、」 48			
Odor		Sewage Ran Petroleum/gas Sulfide Oth	ncid/sour	☐ 1 – Faint ☐		<u></u>	2 – Easily detected		3 – Noticeable from a distance	
Color		☐ Clear         ☐ Brown           ☐ Gray         ☐ Yel           ☐ Green         ☐ Ora           ☐ Red         ☐ Oth	llow inge	in s	- Faint colors in sample bottle □ 2 - sample				– Clearly visible in outfall flow	
Turbidity		See sever	rity	☐ 1 – SI		□ 2 -	Cloudy		– Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper Suds  Petroleum (oil sheer Other:		☐ 1 – Fe	ew/slight; t obvious	2 – Some; indications origin (e.g., possible suds or oil sheen)			- Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials	
INDICATOR  Outfall Damage	CHECK Prese	Spalling, C	<b>DESCRIP</b> racking or Chipping		Peeling F	Paint		СОМ	MENTS	
		Corrosion	·							
Deposits/Stains  Abnormal Vegetation							99.340 000 000 000 000 000 000 000 000 000	<del>1007-1007-1007-100</del>		
Poor pool quality										

Pipe benthic growth

☐ Brown

☐ Orange

Green

Other: