## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

ubwatershed: PB			Outfall ID: 93-29					
Jate & Time: 2:25 5/3/67			Form completed by: SCS MAC					
Temperature (°F): 10°			Rainfall (in.): Last 24 hours:   Last 48 hours: . (5					
Camera:	00-0	340	Photo #s: (PB-029)					
DIAMETER (I	N)	MATERIAL	FLOW	DESCRI	PTION	LAN	ND USE IN AREA	
Diameter:	<b>™</b> R	СР 🔲 СМР	Depth: in.	☐ Trickle		☐ Industrial	☐ Open Space	
\7 in.	□ P	C HDPE	Width: in.	☐ Modera	te	e Urban Residentia	Institutional	
	☐ St	eel Corr. Plastic		☐ Substan	tial	☑ Suburban Residen	itial Other:	
	□ o	her:		No Flov	v	☐ Commercial		
Notes (e.g, Acces	ss to outfall, d	istance and bearing if nece	essary, unable to loca	ite, etc):	• • • • •			
Headwal	. 1							
· From CB	•							
strom CB								
	BIR		3/08	8:37	Com	Orain	48 hus	
NDICATOR	CHECK if Present	DESCRIP	TION		RELA	TIVE SEVERITY IN	DEX (1-3)	
Odor			ncid/sour	☐ 1 – Faint			3 – Noticeable from a	
		☐ Petroleum/gas☐ Sulfide☐ Otl			2 – Easily detected		distance	
			Clear Brown					
Color					2 – Clearly visible in sample bottle		3 – Clearly visible in outfall flow	
		Red Oth		bottle	-			
Turbidity		See seve	rity	☐ 1 – Slight cloudiness	2 – Cloudy		☐ 3 – Opaque	
Floatables		Sewage (Toilet Pape	er, etc.)			Some; indications of	Companie disertions of 2 Companies along (a	
-Does Not Include		Suds  Petroleum (oil sheer	1)	☐ 1 – Few/slight; origin not obvious	origin (e.g., possible suds or oil sheen)		3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
Trash!!		Other:	.,		S	uds or on sneen)	Hoating samtary ma	terrais)
		1						
INDICATOR	CHEC Prese		DESCRIP	TION			COMMENTS	
Outfall Damage		Spalling, C	☐ Spalling, Cracking or Chipping ☐ Peeling Paint ☐ Corrosion					
Deposits/Stains		Oily Fl	Oily Flow Line Paint Other:					
Abnormal Vegetation		☐ Excessive	☐ Excessive ☐ Inhibited					
Poor pool quality		Odors Suds	Odors Colors Floatables Oil Sheen Suds Excessive Algae Other:					
Pipe benthic		☐ Brown	Orange	Green	r:		-	

growth