## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Subwatershed:			Outfall ID: PB-53					
_ate & Time: 9: 67 5 3 07			Form completed by: 555 WAK					
Temperature (°F):			Rainfall (in.): Last 24 hours:					
Camera:	3.5	Will department of the second	Photo #s: dis	posable 3.	05	(PB-053)		
DIAMETER (	IN)	MATERIAL	FLOW		RIPTION		ID USE IN AREA	
iameter:	∏ RO	СР 🔲 СМР	Depth: in.	☐ Trick	le	☐ Industrial	Open Space	
<b>78</b> in.	PV	C HDPE	Width: in.	₩ Mode	erate	Urban Residential	☐ Institutional	
	☐ Ste	eel 🔲 Corr. Plastic		Subst	antial	Suburban Residen	Other:	
	□ Ot	her:		□ No F	low	Commercial		
Notes (e.g, Access to outfall, distance and bearing if ne			essary, unable to locate, etc):					
Headwall From CB In back	yard							
V650L	9 4(Ø CHECK if Present	Z 9.5 DESCRIP	53 an	0" 1		YS Long	DEX (1-3)	
Odor		Sewage Rancid/sour Petroleum/gas Sulfide Other:		☐ 1 — Faint	☐ 2 – F	Easily detected	3 – Noticeable from a distance	
Color		□ Clear         □ Br           □ Gray         □ Ye           □ Green         □ Ort           □ Red         □ Ott	llow ange	1 – Faint color in sample bottle	S 2 - C sample 1	Clearly visible in pottle	3 – Clearly visible in outfal flow	
Turbidity		See severity		☐ 1 – Slight cloudiness	□ 2 – 0	Cloudy	3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pap Suds Petroleum (oil shee Other:		☐ 1 – Few/slight; origin not obvious	ori	Some; indications of gin (e.g., possible ds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, o floating sanitary materials	
INDICATOR	CHECI		DESCRIP	TION			COMMENTS	
Outfall Damage			☐ Spalling, Cracking or Chipping ☐ Peeling Paint					
Deposits/Stains	s 🗆		ow Line Paint Other:					
Abnormal Ugetation		Excessive						
Poor pool quality		Odors Suds						
Pipe benthic growth		Brown	☐ Brown ☐ Orange ☐ Green ☐ Other:					