OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

KON

Subwatershed:	70	•	Outfall ID:	PB-3	58					
Jate & Time:	e & Time: \\ 14 513/07			Form completed by: SCS MAK						
emperature (°F):	2n		Rainfall (in.): Last 24 hours: () Last 48 hours: , 15							
Camera:	3.13		Photo#s: disposable 3,23 (PB-058)							
DIAMETER (IN)	MATERIAL	FLOW		DESCRIPT	<u>ION</u>	LAN	ID US	E IN AREA	
iameter:	Ď RC	СР 🔲 СМР	Depth: in.		☐ Trickle		Industrial		☐ Open Space	
360_in.	☐ PV	C HDPE	Width: in.		☐ Moderate		☐ Urban Residential		☐ Institutional	
¥6 ☐ Stee		1 Corr. Plastic			Substantia	1	☐ Suburban Residential ☐ Commercial		Other:	
V	Ot	her:			No Flow					
all all and a second	Head Full	Ival Y S Bruer	a							
DICATOR	CHECK IF	9/4/08 DESCRIP		3~	~ O		Son'n 48			
IDICATOR	Present					N-L7	IAVE DEVENANT AND	JLX (
Odor		☐ Sewage ☐ Ra ☐ Petroleum/gas ☐ Sulfide ☐ Ot		Faint	2 – Easily detected		☐ 3	- Noticeable from a distance		
Color		☐ Clear ☐ Brown ☐ Yee ☐ Gray ☐ Yeen ☐ Or ☐ Red ☐ Oth	in	samnie	2 – Clearly visible in sample bottle		☐ 3	- Clearly visible in outfall flow		
Turbidity		See seve	rity	□ 1 – S		□ 2 – c] 2 – Cloudy		– Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pap Suds Petroleum (oil shee			igin not obvious		Some; indications of prigin (e.g., possible uds or oil sheen)		- Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
and the second s	10% 9	mbruzil.	a stugant	un	der?	bes	vers living	15	brew and la	
INDICATOR	CHECI Prese		DESCRI	PTION			7	СОМ	MENTS Sur bu	
Outfall Damage		Spalling, C	Spalling, Cracking or Chipping Peeling Paint Corrosion							
Deposits/Stains		Oily F	☐ Oily ☐ Flow Line ☐ Paint ☐ Other:							
Abnormal Vegetation										
Poor pool quality		Odors Suds								
Pipe benthic		Brown	☐ Brown ☐ Orange ☐ Green ☐ Other:							