KOH

OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ckground I	Data							
Oubwatershed:			Outfall ID: PB-64						
Jate & Time:	11:00	513/07	Form completed by: SCS MAK						
Temperature (°F)	64°		Rainfall (in.): Last 24 hours: Last 48 hours: . \						
Camera:	3.18		Photo#s: disposable 3.18 (PB-064)						
DIAMETER (IN)	MATERIAL	FLOW	FLOW <u>DESCRIPTION</u>			LAND USE IN AREA		
Diameter:	RC	СР СМР	Depth: in.	☐ Trickle		☐ Industrial	☐ Open Space		
<u>~15</u> in.	□ PV	C HDPE	Width: in.	☐ Modera	te	Urban Residential	☐ Institutional		
	☐ Ste	eel Corr. Plastic		☐ Substan	tial	🔼 Suburban Resident	tial Other:	_	
-Unknow4	Ot:	her: UNKNOW A		No Flow		☐ Commercial			
Notes (e.g, Acce	ess to outfall, di	stance and bearing if nece	essary, unable to locat	te, etc):					
· Cant	CB see soft	all							
1500 pm 0" rain 48 hrs									
ADICATOR	CHECK if Present	DESCRIP	TION	RELATIVE SEVERITY INDEX (1-3)					
Odor		Sewage Ran Petroleum/gas Sulfide Oth		☐ 1 — Faint	2 – Easily detected		3 – Noticeable from a distance		
Color		☐ Clear ☐ Bro ☐ Gray ☐ Yel ☐ Green ☐ Ora ☐ Red ☐ Oth	llow ange	☐ 1 – Faint colors in sample bottle	2 – Clearly visible in sample bottle		3 – Clearly visible in outf	àll	
Turbidity		See sever		☐ 1 – Slight cloudiness	□2-C	loudy	3 – Opaque		
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheer Other:		☐ 1 – Few/slight; origin not obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)		3 - Some; origin clear (e.g obvious oil sheen, suds, floating sanitary materia	, or	
- 1	no la	Hall; 1/2 1	filled W/s	Whent				Edward voluments	
INDICATOR	CHECK Prese		DESCRIPTION COMMENTS						
Outfall Damage		Spalling, C Corrosion	racking or Chipping						
Deposits/Stains		Oily Fl	ow Line Paint Other:						
Abnormal Uegetation		☐ Excessive	☐ Excessive ☐ Inhibited						
Poor pool quality			Colors						
Pipe benthic growth		Brown	☐ Brown ☐ Orange ☐ Green ☐ Other:						