OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

KEA

| Section 1: Ba | ackground | Data | | | | | | | Michigan Military |
|---|---------------------|--|---|-------------------------------|---------------------------|--|---------------------------|--|---------------------------------|
| ibwatershed: PB | | | Outfall ID: PB-78 | | | | | | |
| Date & Time: 5/23/07 | | | Form completed by: SCS MAC | | | | | | |
| Temperature (°F): | | | Rainfall (in.): Last 24 hours: Last 48 hours: | | | | | | |
| Camera: 1118 Kowk | | | Photo #s: 100-0414 (PB-078) | | | | | | |
| DIAMETER (IN) | | MATERIAL | IAL FLOW | | DESCRIPTION | | LAND USE IN AREA | | |
| Diameter: | ⊠ R | СР СМР | Depth: in. | - | ☐ Trickle | | ☐ Industrial | ☐ Open Space | |
| <u>15</u> in. | □ P | VC HDPE | Width: in. | | ☐ Moderat | te | Urban Residential | ☐ Institutional | |
| ☐ Steel | | teel | | | ☐ Substantial | | Suburban Resident | tial Other: | |
| ☐ Oth | | Other: | | | No flaw | | ☐ Commercial | | |
| Notes (e.g, orig | | | | | 11,0/1 | 200 | | | Imagolisia soomaassa |
| · From CB · Submerged · Pipe end | | | | | | | | | |
| 5. hourged | | | | | | | | | |
| - 0 d | | | | | | | | | |
| a like being | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| BIR glulde 1000 0" can 48 hrs | | | | | | | | | |
|) | BIL | 914108 | 1000 | 0 | 6~ <u> </u> | 0 0 | an 48 | MS | |
| INDICATOR | CHECK if Present | DESCRIP | TION | RELATIVE SEVERITY INDEX (1-3) | | | | | |
| Odor | | ☐ Sewage ☐ Ra ☐ Petroleum/gas ☐ Sulfide ☐ Ot | ncid/sour | ☐ 1 – Faint | | ☐ 2 – E | easily detected | 3 – Noticeable from a distance | |
| Color | | Gray Ye | Gray Yellow Green Orange | | Faint colors sample ttle | | Clearly visible in bottle | 3 – Clearly visible in out | fall |
| Turbidity | | See seve | rity | ☐ 1 – S | Slight ess | 2 – Cloudy | | 3 – Opaque | |
| Floatables -Does Not Include Trash!! | | Suds | Petroleum (oil sheen) | | Few/slight; ot obvious | 2 – Some; indications of origin (e.g., possible suds or oil sheen) | | 3 - Some; origin clear (e. obvious oil sheen, suds floating sanitary mater | s, or |
| | | | | | | | | | |
| INDICATOR CHECK if Present | | | DESCRIPTION | | | | COMMENTS | | |
| Outfall Damage | | Spalling, C | ☐ Spalling, Cracking or Chipping ☐ Corrosion | | | Paint | | | |
| Deposits/Stains | ; | Oily F | Oily Flow Line Paint Other: | | | | | | |
| Abnormal Uegetation | | ☐ Excessive | ☐ Excessive ☐ Inhibited | | | | | | |
| Poor pool qualit | у 🗆 | ☐ Odors ☐ Suds | | | | | | ales and a second | |
| Pipe benthic | | Brown | ☐ Brown ☐ Orange ☐ Green ☐ Other: | | | | | | |

growth