OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ackground	Data			***			****		
Subwatershed:	PB-9	PR-90		Outfall ID: PB-90						
Jate & Time: 12542 513(07			Form completed by: SCS MAK							
Temperature (°F):			Rainfall (in.): Last 24 hours: Dast 48 hours: , (5							
Camera:	<i>y</i>	Photo #s:	Photo #s: (DD-0322 (PB-090)							
DIAMETER (IN)	MATERIAL	FLOW		DESCRI	<u>PTION</u>	LAI	ND USE	E IN AREA	
Diameter:	⊠ R	СР 🔲 СМР	Depth: in.		☐ Trickle		☐ Industrial		Open Space	
<u>\</u> \'\\\ in.	□ Pv	VC HDPE	Width: in.		☐ Moderat	te	Urban Residential		☐ Institutional	
	☐ St	eel Corr. Plastic			Substantial		Suburban Residential		Other:	
		ther:			No Flow		Commercial			
Notes (e.g, Acce	ess to outfall, d	listance and bearing if nece	essary, unable to lo	sary, unable to locate, etc):						
AST F	ZOM EN D FLAR	CB 2TENTM B	Asl~							
	BPR	, (7/3/08	3	105	30	an 0" ra	·'~	48 hrs	
. dicator	CHECK if Present	DESCRIPT	TION			RELA	TIVE SEVERITY IN	DEX (1	1-3)	
Odor		Sewage Ran Petroleum/gas Sulfide Oth	ncid/sour	□ 1 – F	aint 2 – F		asily detected 1 —		– Noticeable from a distance	
Color		□ Clear □ Bro □ Gray □ Yel □ Green □ Ora □ Red □ Othe	low inge	in	Faint colors sample ttle	2 – sample	Clearly visible in bottle		- Clearly visible in outfall flow	
Turbidity		See sever	rity	☐ 1 – S		□ 2-	2 – Cloudy		– Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheen Other:			Few/slight; ot obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)			- Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
INDICATOR	CHEC Prese		DESCRI	PTION				сомі	MENTS	
Outfall Damage	e 🗆	Spalling, Cr	racking or Chipping Peeling Paint							
Deposits/Stains	s 🗆	Oily Flo	w Line Paint Other:							
Abnormal Uegetation		Excessive [☐ Excessive ☐ Inhibited							
Poor pool quality		Odors [Suds								
Pipe benthic		☐ Brown	Orange Green Other:							