OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

'04

Section 1: Background Data										
pwatershed: 773				Outfall ID: New - " - PT3 95						
Date & Time:	8:30	Form completed by: 565 + MAK								
Temperature (°F)	: 143			Rainfall (in.): Last 24 hours: D Last 48 hours: D						
Camera:		Photo #s: WD_0165 (PB-695)								
DIAMETER (IN)	MA	TERIAL	FLOW	<i>i</i>	DESCRIPTION		LAND USE		IN AREA
Diameter:	D R	CP	СМР	Depth: in.		☐ Trickle		☐ Industrial		Open Space
40 in.	P'	VC	HDPE	Width: in.		Moderate		Urban Residential		☐ Institutional
	☐ Steel					Substantial		Suburban Residential		Other:
	Other:							☐ Commercial		
Notes (e.g, origin of autfall, if known):										
CARHBASIN IN YARD										
BTR 9/3/08 8:30 m 0" rain 48 hus										
	CHECK if		11 31		7, 21) on				
INDICATOR	Present	DESCRIPTION RELATIVE SEVERITY INDEX (1-3)								-3)
Odor		☐ Se ☐ Pe ☐ Su	troleum/gas	ncid/sour	☐ 1 – Faint ☐ 2		□ 2 – E	Easily detected 3		- Noticeable from a distance
Color		☐ Cl ☐ Gr ☐ Gr	ay	low nge			2 – Clearly visible in sample bottle		3 – Clearly visible in outfall flow	
Turbidity			See sever	ity	☐ 1 – Slight cloudiness ☐ 2 –		□ 2 – C	Cloudy 3		- Opaque
Floatables -Does Not Include Trash!!		Su	troleum (oil sheen			origin not obvious or		Some; indications of gin (e.g., possible ds or oil sheen)		Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)
INDICATOR		CHECK if Present			DESCRIPTION			COMMENTS		
Outfall Damage			☐ Spalling, Cracking or Chipping ☐ Peeling Paint ☐ Corrosion				Paint		Planta de la companya del companya de la companya del companya de la companya de	
Deposits/Stains			☐ Oily ☐ Flo	nt [Other:					
Abnormal Vegetation			Excessive [TROUGH 1977 STORE (** 1870 F. STORE 1881 STO	
Poor pool quality	y 🗆		☐ Odors ☐ Suds ☐	Floatables Oil Sheen Other:					VANATURE CEREBOOK III OO 1870 WASHING CANADA	
Pipe benthic growth			☐ Brown ☐ Orange ☐ Green			☐ Other	;			