## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ackground I	Data							
'ubwatershed:	PR	-D	Outfall ID: PRD-4						
Date & Time: 8:55 5/23/07			Form completed by: SUS MAK						
Temperature (°F)	: 650		Rainfall (in.): Last 24 hours: O Last 48 hours:						
Camera:	IC	odak	Photo #s: 100-0382 (PRD-004)						
DIAMETER (IN) MATERIAL			FLOW <u>DESCRIPTION</u>			LAN	LAND USE IN AREA		
Diameter:	Ď <b>X</b> RC	CP CMP	Depth: in.	Trickle		☐ Industrial		Open Space	
13 in.	□ PV	C HDPE	Width: in.	☐ Modera	te	Urban Residential		☐ Institutional	
	☐ Ste	eel Corr. Plastic		☐ Substantial		Šuburban Residential		Other:	
	☐ Oti	her:		☐ No Flow	/ Commercial				
Notes (e.g, Acce	ess to outfall, di	stance and bearing if nece	ssary, unable to locate, e	tc):			L		
· From C	8								
	G-20 CHECK IF	8124 <i> 0</i> 8		0" re		18 hu		TR	
INDICATOR	Present	DESCRIPT	TION		RELAT	TVE SEVERITY IN	DEX (1	-3)	
Odor		☐ Sewage ☐ Rar☐ Petroleum/gas☐ Sulfide ☐ Oth		1 – Faint	2 – Easily detected		3 – Noticeable from a distance		
Color		☐ Clear         ☐ Bro           ☐ Gray         ☐ Yel           ☐ Green         ☐ Ora           ☐ Red         ☐ Othe	low nge	1 – Faint colors in sample bottle		2 – Clearly visible in sample bottle		- Clearly visible in outfall low	
Turbidity		See sever	1111	l – Slight Idiness	□ 2 – 0	Cloudy	□ 3 -	- Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds  Petroleum (oil sheen Other:		l – Few/slight; in not obvious	ori	2 – Some; indications of origin (e.g., possible suds or oil sheen)		Some; origin clear (e.g., obvious oil sheen, suds, or loating sanitary materials)	
INDICATOR  Outfall Damage  Deposits/Stains	e $\square$	nt Spalling, Corrosion	DESCRIPTION Facking or Chipping Dow Line Paint	N Peeling I	Paint		COMP	1ENTS	
Abnormal Vegetation		☐ Excessive							
Poor pool qualit	у 🗆		Colors Floatables Oil Sheen Excessive Algae Other:						

Green

Other:

☐ Orange

☐ Brown

Pipe benthic

growth