OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ckground	Data						
ubwatershed:		SB	Outfall ID: 5B-3					
Date & Time:	& Time: 12:40 5/23/07			Form completed by: SCS MAK				
Temperature (°F)	: 79.		Rainfall (in.): Last 24 hours: Last 48 hours:					
Camera:	Y	ODAK	Photo #s: 10	Photo #s: 100_(408 (5B-003)				
DIAMETER (IN)	MATERIAL	FLOW	DESCI	RIPTION	LAN	ID USE IN AREA	
Diameter:	☐ R	СР СМР	Depth: in.	☐ Trick	le	☐ Industrial	Open Space	
_15≈ in.	Ď Þ≀	VC HDPE	Width: in.	☐ Mode	erate	☐ Urban Residential	☐ Institutional	
	☐ St	eel Corr. Plastic		☐ Subst	antial	Suburban Resident	tial Other:	
	□ Oi	ther:		No Fl	ow	☐ Commercial		
·Into a		0.10	1 /			0" ra	^ -	
15	182	9/6	108	2:30)	40h	'^	
₄ NDICATOR	CHECK if Present	DESCRIPTION RELATIVE SEVERITY INDEX (1-3)						
Odor		Sewage Ra Petroleum/gas Sulfide Oti	ncid/sour ner:	☐ 1 — Faint	☐ 2 - I	Easily detected	3 – Noticeable from a distance	
Color		☐ Clear ☐ Bro ☐ Gray ☐ Ye ☐ Green ☐ Ora ☐ Red ☐ Oth	llow ange	1 – Faint colors in sample bottle	$\begin{bmatrix} 2 - 6 \\ \text{sample} \end{bmatrix}$	Clearly visible in bottle	3 – Clearly visible in outfall flow	
Turbidity		See seve	rity	☐ 1 – Slight cloudiness	□ 2 - 0	Cloudy	3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper Suds Petroleum (oil sheer Other:		☐ 1 – Few/slight; origin not obvious	or	Some; indications of igin (e.g., possible ds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
						<u> </u>		
INDICATOR	INDICATOR CHECK if Present DESCRI			TION			COMMENTS	
Outfall Damage		Spalling, Cracking or Chippin Corrosion		g Peeling Paint				
Deposits/Stains		Oily Fl	ow Line Paint Other:					
Abnormal Uegetation		☐ Excessive	☐ Inhibited					
Poor pool quality			☐ Odors ☐ Colors ☐ Floatables ☐ Oil Sheen ☐ Suds ☐ Excessive Algae ☐ Other:					
Pipe benthic growth		☐ Brown	☐ Brown ☐ Orange ☐ Green ☐ Other:					