OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET



Section 1: Ba	ckground l	Data									
bwatershed: 5B				Outfall ID: 5B-7							
Date & Time: 12:56 5123/07				Form completed by: SCS MAK							
Temperature (°F):				Rainfall (in.): Last 24 hours: C Last 48 hours: C							
Camera:	8	dak	Photo #s: 100-0411 (SB-007)								
DIAMETER (IN)	MA	TERIAL	FLOW	1	DESCRI	PTION	<u>LA</u>	ND USE IN	AREA	
Diameter:	🔀 RO	CP CP	□СМР	Depth: in.		☐ Trickle		☐ Industrial		Open Space	
12_ in.	☐ PV	'C	☐ HDPE	Width: in.		☐ Moderate		Urban Residentia	1	☐ Institutional	
	☐ St	eel	Corr. Plastic					Suburban Resident		tial Other:	
	Ot	her:				No Flow		☐ Commercial			
Votes (e.a. Acce			and bearing if nece	ssary unable to lo	veate etc):						
	TW		91						C	"shir.	
15	1 00	,	1/3	9108 <u> </u>	X	"BOD"	L	2146 P~	~	ysha	
ındicator	CHECK if Present	DESCRIPT		ON REL		RELA	TIVE SEVERITY INDEX (1-3)				
Odor		Sewage Rancid/s Petroleum/gas Sulfide Other:			□ 1 – I	☐ 1 – Faint ☐ 2 –		Easily detected		oticeable from a ance	
Color		□ Clear □ Brow □ Gray □ Yell □ Green □ Orar □ Red □ Other		low nge	in	Faint colors sample	2 – Clearly visible in sample bottle		3 - Cl	early visible in outfall	
Turbidity			See sever	ity	☐ 1 – S		☐ 2 —	Cloudy	□ 3 – Op	paque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper Suds Petroleum (oil sheen Other:				not obvious origin (e.g.,		Some; indications of igin (e.g., possible ds or oil sheen)	obv	me; origin clear (e.g., ious oil sheen, suds, or ting sanitary materials	
INDICATOR	CHEC			DESCRI	PTION				COMMEN	ITS	
Outfall Damage	Prese	IIL	☐ Spalling, Cracking or Chipping ☐ Peeling Paint ☐ Corrosion								
Deposits/Stains				w Line Paint Other:							
Abnormal Vegetation			☐ Excessive [Inhibited		January 1, 100					

Odors Suds

☐ Brown

Poor pool quality

Pipe benthic

growth

Colors Excessive Algae

☐ Orange

☐ Floatables

☐ Green

Oil Sheen

Other:

Other: