OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ackground I	D ata			_		ert	
Subwatershed:	UB	The state of the s	Outfall ID: WT3- 18					
ate & Time: \$19/27			Form completed by: 5 < 5					
Temperature (°F)):		Rainfall (in.): Last 24 hours:					
Camera:			Photo#s: 3624 (WB-618)					
DIAMETER (IN)	MATERIAL	FLOW	DESCRI	PTION	LAN	D USE IN AREA	
Diameter:	□ (RC	СР 🗌 СМР	Depth: in.	☐ Trickle	ute Urban Residential		Open Space	
\ in.	□ PV	C HDPE	Width: in.	☐ Moderat			☐ Institutional	
	☐ Ste	eel Corr. Plastic		☐ Substant			ial Other:	
	Ot	her:		No Flow				
Notes (e.g, Acce	ess to outfall, di	stance and bearing if nece	essary, unable to loc	cate, etc):				
Heude Pipe C	ew)	,)		subnegel				
(DICATOR	CHECK if Present	24 08 2 DESCRIP	: 30 Tion	O" rair		VE SEVERITY INC	DEX (1-3)	
Odor		Sewage Rancid/sour Petroleum/gas Other:		☐ 1 — Faint	2 – Easily detected		☐ 3 – Noticeable from a distance	
Color		☐ Clear ☐ Brown ☐ Gray ☐ Yellow ☐ Green ☐ Orange ☐ Red ☐ Other:		1 – Faint colors in sample bottle	2 – Clearly visible in sample bottle		☐ 3 – Clearly visible in outfall flow	
Turbidity		See severity		1 – Slight cloudiness	2 – Cloudy		3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper Suds Petroleum (oil sheer Other:		☐ 1 – Few/slight; origin not obvious	origi	me; indications of n (e.g., possible or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
INDICATOR CHECK if Present			DESCRI	DESCRIPTION COMMENTS				
Outfall Damage	e 🗆	Spalling, C	Cracking or Chipping	ing Peeling Paint				
Deposits/Stains [Oily F	ow Line Pain	t Other:				
Abnormal Uegetation		Excessive	☐ Excessive ☐ Inhibited					
coor pool quality			Odors Colors Oil Sheen Suds Excessive Algae Other:					
Pipe benthic growth		Brown	☐ Brown ☐ Orange ☐ Green ☐ Other:					