## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET



growth

☐ Brown

☐ Orange

☐ Green

Other:

Section 1: Ba		· · · · · · · · · · · · · · · · · · ·				
Subwatershed:	لالما		Outfall ID: W8-27			
Date & Time:	9:57	41/25/07	Form completed by: MAK			
Temperature (°F)	: 60,		Rainfall (in.): Last 24 hor	urs: D Last	48 hours:	
Camera:			Photo #s: (WB-027)			
DIAMETER (	IN)	MATERIAL	FLOW	DESCRIPTIO	N LAI	ND USE IN AREA
Diameter:	□ R	CP CMP	Depth: in.	☐ Trickle	☐ Industrial	☐ Open Space
in.	□ PV	C HDPE	Width: in.	☐ Moderate	☐ Urban Residentia	l Institutional
	□ St	eel 🗖 Corr. Plastic		☐ Substantial	Suburban Resider	ntial Other:
	□ O1	her:		No Flow	☐ Commercial	
From de	tention b	_	essary, unable to locate, etc):			
	BT	2 9/3/08	12:48	2.00	O'Irain 4	8 hrs
INDICATOR	CHECK if Present	DESCRIPT	TION	RELATIVE SEVERITY INDEX (1-3)		
Odor		Sewage Rar Petroleum/gas Sulfide Oth	ncid/sour	Faint 🔲	2 – Easily detected	3 – Noticeable from a distance
Color		☐ Clear         ☐ Bro           ☐ Gray         ☐ Yel           ☐ Green         ☐ Ora           ☐ Red         ☐ Othe	low in ho		2 – Clearly visible in pple bottle	3 – Clearly visible in outfall flow
Turbidity		See sever	rity	- 111	2 – Cloudy	☐ 3 — Opaque
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheen Other:	□ 1 – F	Few/slight; ot obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)
INDICATOR	CHEC Prese		DESCRIPTION			COMMENTS
Outfall Damage			☐ Spalling, Cracking or Chipping ☐ Peeling Paint ☐ Corrosion			
Deposits/Stains			w Line Paint Other:			
Abnormal Vegetation		-				
Poor pool quality						
Pipe benthic		[] Prove	□ Oranga □ Graan	Othory		