## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Bac	THE OWNER OF THE OWNER OWNER OF THE OWNER OW	Data		-		(1	1			
Jbwatershed: UB			Outfall ID: WB-44							
Date & Time:	5 5/7/07	Form completed by: SCS								
Temperature (°F):			Rainfall (in.): Last 24 hours:							
Camera:	Photo #s: 367 (WB-044)									
DIAMETER (IN) MATERIAL		MATERIAL	FLOW		DESCRIP	MOIT	LAND USE IN AREA			
Diameter:	□ RO	СР 🔲 СМР	Depth: in.		☐ Trickle		☐ Industrial		Open Space	
in.	□ PV		Width: in.		☐ Moderat	:e	Urban Residential	1 [	☐ Institutional	
	□ St	teel CRP			Substant	ial	Suburban Residential		Other:	
,		ther:			MUN	15	Commercial			
Notes (e.g, origin				***************************************						
FLA	220	200								
3TR 8/29/08 11:20 0" rain 48 hrs										
INDICATOR	CHECK if Present	DESCRIPT	rion			RELA	TIVE SEVERITY IN	DEX (1-	3)	
Odor		Petroleum/gas	Petroleum/gas		Faint .	2 – Easily detected		1	Noticeable from a listance	
Color	, 🗆 .	☐ Clear         ☐ Bro           ☐ Gray         ☐ Yell           ☐ Green         ☐ Ora           ☐ Red         ☐ Other	llow	in	Faint colors sample ttle		2 – Clearly visible in sample bottle		Clearly visible in outfall low	
Turbidity		See sever	ity	☐ 1 – S	_	□ 2 – 0	2 – Cloudy		Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheen Other:		☐ 1 — F	Few/slight; ot obvious	or	2 – Some; indications of origin (e.g., possible suds or oil sheen)		Some; origin clear (e.g., bvious oil sheen, suds, or loating sanitary materials)	
A CONTRACTOR OF THE PROPERTY O		Betting the property of the second								
INDICATOR CHECK if Present			DESCRIPTION COMMENTS							
Outfall Damage		Spalling, Cr Corrosion	acking or Chipping Peeling Paint							
Deposits/Stains		Oily Flo	Oily Flow Line Paint Other:							
Abnormal Uegetation		☐ Excessive [	□ Excessive □ Inhibited							
Poor pool quality										

☐ Green

Other:

☐ Brown

☐ Orange

Pipe benthic growth