OK
ICEA

Section 1: Background Data

Subwatershed: WB	Outfall ID: WB-58
Date & Time: 11:12 5/9/07	Form completed by: SCS
Temperature (°F):	Rainfall (in.): Last 24 hours: 0 Last 48 hours: 0
Camera:	Photo #s: 3650 (WB-058)

DIAMETER (IN)	MATERIAL		FLOW	DESCRIPTION	LAND USE IN AREA	
Diameter: 18 in.	☑ RCP ☐ PVC ☐ Steel ☐ Other: _____	☐ CMP ☐ HDPE ☐ Corr. Plastic	Depth: ____ in. Width: ____ in.	☐ Trickle ☐ Moderate ☐ Substantial ☑ No Flow	☐ Industrial ☐ Urban Residential ☑ Suburban Residential ☐ Commercial	☐ Open Space ☐ Institutional Other: _____

Notes (e.g.., Access to outfall, distance and bearing if necessary, unable to locate, etc):

Flared end
FROM LB

BTR 8/29/08   12:00   0" rain 48 hrs

INDICATOR	CHECK if Present	DESCRIPTION	RELATIVE SEVERITY INDEX (1-3)		
Odor	☐	☐ Sewage ☐ Rancid/sour ☐ Petroleum/gas ☐ Sulfide ☐ Other:	☐ 1 – Faint	☐ 2 – Easily detected	☐ 3 – Noticeable from a distance
Color	☐	☐ Clear ☐ Brown ☐ Gray ☐ Yellow ☐ Green ☐ Orange ☐ Red ☐ Other:	☐ 1 – Faint colors in sample bottle	☐ 2 – Clearly visible in sample bottle	☐ 3 – Clearly visible in outfall flow
Turbidity	☐	See severity	☐ 1 – Slight cloudiness	☐ 2 – Cloudy	☐ 3 – Opaque
Floatables -Does Not Include Trash!!	☐	☐ Sewage (Toilet Paper, etc.) ☐ Suds ☐ Petroleum (oil sheen) ☐ Other:	☐ 1 – Few/slight; origin not obvious	☐ 2 – Some; indications of origin (e.g., possible suds or oil sheen)	☐ 3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)

INDICATOR	CHECK if Present	DESCRIPTION	COMMENTS
Outfall Damage	☐	☐ Spalling, Cracking or Chipping ☐ Peeling Paint ☐ Corrosion	
Deposits/Stains	☐	☐ Oily ☐ Flow Line ☐ Paint ☐ Other:	
Abnormal Vegetation	☐	☐ Excessive ☐ Inhibited	
Poor pool quality	☐	☐ Odors ☐ Colors ☐ Floatables ☐ Oil Sheen ☐ Suds ☐ Excessive Algae ☐ Other:	
Pipe benthic growth	☐	☐ Brown ☐ Orange ☐ Green ☐ Other:	