## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

Section 1: Ba	ickground l	Data					TAT	
Tubwatershed: WB			Outfall ID: WB-64 3					
ate & Time:	10:	18 5/9/07	Form completed by: SCS					
Temperature (°F):	:	-	Rainfall (in.): Last 24 hours: $\mathcal O$ Last 48 hours: $\mathcal D$					
Camera:			Photo #s:	942 (	EW.	-063)		
DIAMETER (	IN)	MATERIAL	FLOW	DESCRI	C-14 15 12 15 16 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18		ID USE IN AREA	
Diameter:	DXRC	СР 🗌 СМР	Depth: in.	☐ Trickle		☐ Industrial	Open Space	
12_in.	PV	VC HDPE	Width: in.	☐ Moderat	te	Urban Residential	☐ Institutional	
	☐ Ste	eel Corr. Plastic	:	Substant	tial	Suburban Residen	tial Other:	
	Ot	ther:		□ <b>V</b> No Flow	ow Commercial			
	BTR	8/24/08	12:35	0" ra	in 48	40		
DICATOR	CHECK if Present	DESCRIP	TION	RELATIVE SEVERITY INDEX (1-3)				
Odor		Sewage Ra		☐ 1 — Faint	☐ 2 – Easily detected		3 – Noticeable from a distance	
Color		☐ Clear         ☐ Brown           ☐ Gray         ☐ Ye           ☐ Green         ☐ Ora           ☐ Red         ☐ Oth	ellow	1 – Faint colors in sample bottle	☐ 2 – Clearly visible in sample bottle		3 – Clearly visible in outfall flow	
Turbidity		See seve		☐ 1 – Slight cloudiness	2 – Cloudy		☐ 3 — Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper   Suds   Petroleum (oil sheet   Other:		☐ 1 – Few/slight; origin not obvious	2 – Some; indications of origin (e.g., possible suds or oil sheen)		3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
	**************************************				<u> </u>		<u> </u>	
INDICATOR	CHECI Prese		DESCRIPT	TION			COMMENTS	
Outfall Damage		Spalling, C	acking or Chipping					
Deposits/Stains		Oily Fl	w Line Paint Other:					
Abnormal Vegetation		☐ Excessive						
Poor pool quality			☐ Odors     ☐ Colors     ☐ Floatables     ☐ Oil Sheen       ☐ Suds     ☐ Excessive Algae     ☐ Other:					
Pipe benthic		□ Proum	□ Orange □	Green D Other				

growth

Brown

Orange

☐ Green

Other: