## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

(S)C.

Section 1: Ba	ckground D	ata						
े ıbwatershed:	(	WB		Outfall ID: W8-77				
ate & Time: 3:00 5123107			Form completed by: SCS MAK					
Temperature (°F):		Rainfall (in.): Last 24 hours:						
Camera: KBDaK			Photo #s: 100-0429 (WB-677)					
DIAMETER (	IN)	MATERIAL	FLOW	DESCRI	<u>IPTION</u>	LAN	ND USE IN AREA	
Diameter:	RC:	Р 🗌 СМР	Depth: in.	Trickle		☐ Industrial	☐ Open Space	
NS in.	□ PV	C HDPE	Width: in.	☐ Modera	ate	Urban Residential	l Institutional	
	☐ Stee	el Corr. Plastic		☐ Substantial		Suburban Residential	ntial Other:	
	Oth	er:		☐ No Flo	w	☐ Commercial		
· From · Head w	91) MH							
(DICATOR	CHECK if Present	8/29/08 DESCRIP		3:00 p.~	^	TIVE SEVERITY IN		
Odor		☐ Petroleum/gas	Petroleum/gas		2 – Easily detected		3 – Noticeable from a distance	
Color		☐ Clear         ☐ Brown           ☐ Gray         ☐ Yellow           ☐ Green         ☐ Orange           ☐ Red         ☐ Other:		☐ 1 – Faint colors in sample bottle	2 – Clearly visible in sample bottle		3 – Clearly visible in outs	
Turbidity		See sever	See severity		2 – Cloudy		☐ 3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheen Other:		☐ 1 – Few/slight; origin not obvious	or	Some; indications of gin (e.g., possible ds or oil sheen)	3 - Some; origin clear (e.gobvious oil sheen, suds floating sanitary materi	
INDICATOR	CHECK Preser	nt	DESCRI				COMMENTS	
Outfall Damage		Corrosion						
Deposits/Stains		Oily Flo	Oily Flow Line Other:					
Abnormal Vegetation								
Poor pool qualit	y   🗆		Colors [	Floatables Oil				

Pipe benthic growth

Brown

☐ Orange

☐ Green

Other: