## OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET



Section 1: Ba	ackground	Data	T		***************************************				
Ibwatershed:         WB           Date & Time:         \\'.5\         4/(1/07)		Outfall ID: WB-104							
Date & Time:	11:51	Form completed by: SC5 + MAK							
Temperature (°F)	45°		Rainfall (in.): L	ast 24 hou	urs: O	Last 48 h	ours: O		
Camera:	KUDA	Photo #s:0179			(MB-104)				
DIAMETER (	DIAMETER (IN) MATERI		FLOW		DESCRI	PTION	LAND USE IN AREA		
Diameter:	FD R	CP CMP	Depth: in.		☐ Trickle		☐ Industrial	☐ Open Space	
in.	☐ PVC ☐ HDPE		Width: in.	☐ Moderate		te	Urban Residential	I Institutional	
		eel		☐ Substant		tial	Suburban Residen	ntial Other:	
		her:		None			☐ Commercial		
Notes (e.g, origi	in of outfall, if	known):			1	NOTHING THE WAS ARREST AT A STATE OF			
- Flared end									
- rip 13P									
- DWH Asuq									
	BTR	9/0/00	7 G			01/2	an 48L		
	15 1 10	1/0//08	82	50	an	O V	701	13	
INDICATOR	CHECK if Present	DESCRIP	TION	RELATIVE SEVERITY INDEX (1-3)					
Odor		☐ Sewage ☐ Rancid/sour ☐ Petroleum/gas ☐ Other:		□ 1 – F	Faint Faint	2 – Easily detected		☐ 3 – Noticeable from a distance	
Color			llow ange	in	Faint colors sample ttle	2 – 0 sample	Clearly visible in bottle	3 – Clearly visible in outfall flow	
Turbidity		See sever	rity	☐ 1 – S cloudine		2 – Cloudy		☐ 3 — Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Pape Suds Petroleum (oil sheer Other:			Few/slight; ot obvious	or	Some; indications of gin (e.g., possible ds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials)	
INDICATOR	CHECI Prese		DESCRIPTION					COMMENTS	
Outfall Damage		Spalling, Corrosion	racking or Chipping Peeling Paint						
Deposits/Stains		Oily Flo	ow Line	Line Paint Other:					
Abnormal Vegetation		☐ Excessive	Inhibited						
Poor pool qualit	у 🗆		Colors						

Other:

☐ Green

☐ Brown

☐ Orange

Pipe benthic

growth