OUTFALL RECONNAISSANCE INVENTORY / COLLECTION FIELD SHEET

OU GA

Section 1: Ba	ckground l	Data					001	
bwatershed:		WB	Outfall ID: 🕠	Outfall ID: WB-117				
Date & Time:		5/23/67	Form completed by: SCS MAK					
Temperature (°F):			Rainfall (in.): Last 24 hours: D Last 48 hours: D					
Camera:	\	coonk	Photo #s:	0-0397	(V	113-117)		
DIAMETER (IN)	MATERIAL	FLOW	DESCRI	PTION	LAND USE IN AREA		
iameter:	□ RC	СР 🔲 СМР	Depth: in.	Trickle		☐ Industrial	Open Space	
15 in.	□ PV	C HDPE	Width: in.	☐ Modera	te	☐ Urban Residential	I Institutional	
	Sto	eel Corr. Plastic		Substan	tial	Suburban Residen	otial Other:	
	По	her:		☐ No Flow	v	☐ Commercial		
·Flared	eng 							
STIL 9/2			108 11:20 am 0" rain 48 hs					
INDICATOR	Present	DESCRIP	DESCRIPTION		RELATIVE SEVERITY INDEX (1-3)			
Odor		Sewage Ra Petroleum/gas Sulfide Ott	ncid/sour her:	☐ 1 – Faint	☐ 2 – Easily detected		3 – Noticeable from a distance	
Color		☐ Clear ☐ Brown ☐ Gray ☐ Ye ☐ Green ☐ Ora ☐ Red ☐ Oth	llow ange	1 – Faint colors in sample bottle	2 – Clearly visible in sample bottle		3 – Clearly visible in outfall flow	
Turbidity		See seve	rity	1 – Slight cloudiness	□ 2 – 0	Cloudy	3 – Opaque	
Floatables -Does Not Include Trash!!		Sewage (Toilet Paper Suds Petroleum (oil sheer Other:		1 – Few/slight; origin not obvious	or	Some; indications of gin (e.g., possible ds or oil sheen)	3 - Some; origin clear (e.g., obvious oil sheen, suds, or floating sanitary materials	
INDICATOR	CHECI Prese		DESCRI	PTION			COMMENTS	
Outfall Damage			Spalling, Cracking or Chipping					
Deposits/Stains		Oily Fl	w Line Paint Other:					
Abnormal		☐ Excessive	T 1.1.11.141	Inhibited				

☐ Odors ☐ Suds

Brown

Poor pool quality

Pipe benthic

growth

Colors Excessive Algae

☐ Orange

☐ Floatables

Green

Oil Sheen
Other:

Other: