

CURRENT OWNER		TOPO TYPE	UTILITY	STREET	LOCATION	CURRENT ASSESSMENT								1006 EAST LONGMEADOW								
CLARK LAURA S 168 HAMPDEN RD EAST LONGMEADOW MA 01028 GIS ID F_391346_2846831		TOPO WET	EASEMENT	TRAFFIC	CORNER	Description	Code	Appraised	Assessed													
						RESIDNTL.	101	174700	174,700													
						RES LAND	101	127300	127,300													
		DRAINAGE		VIEW	COMMUNITY																	
		SUPPLEMENTAL DATA																				
		Alt Prcl ID SP Permit Chapter Land OC Dates In+Ex FY Mailed		Received NIA Field 8 Field 9 Field 10 Assoc Pid#		Total		302,000	302,000													
RECORD OF OWNERSHIP		BK-VOL/PAGE		SALE DATE	Q/U	V/I	SALE PRICE	VC	PREVIOUS ASSESSMENTS (HISTORY)													
CLARK LAURA S CLARK RICHARD A,LIFE ESTATE CLARK RICHARD A + DORIS B		14733	0319	12-27-2004	U	I	100	1A	Year	Code	Assessed	Year	Code	Assessed	Year	Code	Assessed					
		09444	0373	04-09-1996	U	I	1		2025	101	155,000	2024	101	142,600	2023	101	130,300					
		02524	0348	01-31-1957	U	I	0			101	127,300		101	127,300		101	115,500					
									Total		282,300	Total		269,900	Total		245,800					
EXEMPTIONS				OTHER ASSESSMENTS				This signature acknowledges a visit by a Data Collector or Assessor														
Year	Code	Description		Amount	Code	Description	YEAR											Amount	Comm Int			
											APPRaised VALUE SUMMARY											
Total																						
ASSESSING NEIGHBORHOOD										Appraised BLDG. Value (Card) 174,700 Appraised Xf (B) Value (Bldg) 0 Appraised Ob (B) Value (Bldg) 0 Appraised Land Value (Bldg) 127,300 Special Land Value 0 Total Appraised Parcel Value 302,000 Valuation Method C Adjustment Net Total Appraised Parcel Value 302,000												
Nbhd		Nbhd Name		Tracing			Batch															
0001				101			MG															
NOTES																						
BMT FLOOR 90% EARTH																						
BUILDING PERMIT RECORD										VISIT / CHANGE HISTORY												
Permit Id	Issue Date	Type	Description	Amount	Insp Date	% Comp	Date Comp	Comments	Date	Type	Is	Id	Cd	Purpose/Result								
202200836	03-15-2022	25	WINDOWS	6,008	06-13-2022	100	06-13-2022	RPLC 3 WINS & 3 B	05-04-2017			317	15	PERMIT VISIT								
201602351	08-17-2016	25	WINDOWS	5,987	05-04-2017	100	05-04-2017	CK FOR GENERAT	08-23-2013			317	15	PERMIT VISIT								
201201828	04-19-2012	7	REMODEL	10,000		0	05-15-2014	KITCHEN NVC	06-08-2012			317	15	PERMIT VISIT								
201102663	01-01-2012	8	RENOVATION	30,000		0	05-15-2014	NEW FLOORS, INT	04-02-2006			311	14	INSPECTED								
									03-23-2006			311	2	MEASURED								
									12-20-1999			247	3	MEAS+INSPCTD								
									04-01-1992			170	3	MEAS+INSPCTD								
LAND LINE VALUATION SECTION																						
B	Use Co	Description	Zone	D	Fronta	Depth	Land Units	Unit Price	I. Fact	S.A.	Ac Di	C. Fact	St. Idx	Adj	Notes	Special Pricing		Size A	Adj Unit Pric	Land Value		
1	101	ONE FAM	RA				25,000 SF	4.71	1.200	7	LAND	1.00	MG	1.00			0 TRF2 0.9	1.000	5.09	127,300		
Total Card Land Units							0.57 AC	Parcel Total Land Area: 0.57							Total Land Value							127,300

The diagram is a floor plan of a building, likely a school or institutional facility, showing various rooms and corridors. The plan is color-coded: blue for main rooms and red for other areas.

- Top Section:** A large rectangular area labeled **STG** (Staircase) in red. It has dimensions of 16, 16, 28, 3, and 12.
- Left Section:** A large rectangular area labeled **SFL**, **FFL**, and **BMT** in blue. It has dimensions of 9, 13, 12, 5, 8, 8, 6, 12, 8, 11, 12, 5, 5, 11, 12, 5, 7, 7, 16, and 30.
- Right Section:** A rectangular area labeled **EFP** (Elevator Platform) in red. It has dimensions of 4, 5, 11, 12, 8, 8, 6, and 12.
- Bottom Section:** A complex area with multiple rooms and corridors. It includes:
 - A central area labeled **SFL** and **EFP** in blue.
 - A room labeled **SFL** in blue.
 - A room labeled **FFL** (Floor Level) in blue.
 - A room labeled **EFP** in red.
 - Dimensions for this section include 11, 12, 5, 5, 11, 12, 5, 7, 7, 16, 2, 23, 7, and 12.

A photograph of a two-story red wooden house with a gabled roof. The house has several windows, some with white frames. An American flag is flying on a pole to the right of the house. The house is surrounded by green trees and foliage.A two-story red wooden house with white trim, a grey roof, and a chimney. The house has several windows, some with white curtains. A large tree is on the left, and a flagpole with an American flag is on the right. The house is surrounded by green grass and trees.